

NEVER touch metal fasteners with metal package opening devices when opening packages of explosive materials.

NEVER mix different explosives in the same package.

PROTECTING EXPLOSIVE MATERIALS

ALWAYS insure that there are no foreign objects, loose powder or moisture in a non-electric detonator before inserting safety fuse/detonating cord.

NEVER investigate the contents of a detonator.

NEVER pull wires, safety fuse, shock tube, or detonating cord out of any detonator or delay device.

NEVER strike explosive materials with, or allow them to be hit by hard, heavy objects.

NEVER subject explosive materials to excessive impact or friction.

NEVER allow loaded firearms in the vicinity of, nor shoot near, explosive materials, magazines, or vehicles loaded with explosive materials.

USING EXPLOSIVE MATERIALS - GENERAL

Protecting Yourself:

ALWAYS keep explosive materials away from food, eyes, and skin.

ALWAYS avoid exposure to excessive noise from detonations.

ALWAYS initiate the detonation from a position outside the blast area away from any area where shrapnel might occur.

ALWAYS remain in a position away from the blast area until post blast fumes, dust, or mist have subsided.

NEVER position yourself near any explosive materials when initiating a detonation.

NEVER breathe dust or vapors from explosive materials, or fumes from detonated or burnt explosives.

Protecting Others:

ALWAYS clear the immediate area of persons.

THINK SAFETY WORK SAFE 19



ALWAYS post guards or place barriers to prevent access to the blast area.

ALWAYS sound adequate warning prior to initiating the detonation.

NEVER initiate a detonation without a positive signal from the person in charge.

NEVER permit anyone to handle explosive materials or position themselves near explosive materials when a detonation is to be initiated.

Protecting the Blast Area:

ALWAYS clear the immediate area of vehicles, equipment, and extra explosive materials.

NEVER allow any source of initiation within 50 feet of a detonation site except approved safety fuse lighters if initiation is to be a non-electric system.

USING EXPLOSIVE MATERIALS - ELECTRIC DETONATORS

ALWAYS test the circuit for continuity and proper resistance, using a blasting galvanometer or an instrument specifically designed for testing electric detonators and circuits containing them.

ALWAYS fire electric detonators with firing currents or voltage in the range recommended by the manufacturer.

ALWAYS keep electric detonator wires or lead wires disconnected from the power source and shunted until ready to test or fire.

ALWAYS keep the firing circuit completely insulated from the ground or other conductors.

ALWAYS be sure that all wire ends are clean before connecting.

NEVER set up a detonation near electric power lines unless the firing line and detonator wires are anchored or are too short to reach the power line(s).

NEVER handle or use electric detonators:

- When stray currents are present.
- During electrical storms.
- If static electricity is present.

THINK SAFETY WORK SAFE





NEVER use any instruments, such as electrician's meters, that are not specifically designed for testing blasting circuits or detonators. Such meters could produce sufficient electrical energy to prematurely initiate electric detonators.

NEVER use electric detonators near radio-frequency transmitters, except those approved for use in RF environments.

NEVER mix electric detonators made by different manufacturers in the same circuit.

NEVER mix electric detonators of different types in a circuit, even if made by the same manufacturer, unless such as is approved by the manufacturer.

NEVER use aluminum wire in a blasting circuit.

NEVER open blasting machines or handle batteries near electric detonators.

NEVER make final hookup to power source until all personnel are clear of the blast area.

NEVER load or use primary explosives, such as lead azide, in copper shells.

NEVER crimp electric detonators over the mid-section that contains primary explosives.

USING EXPLOSIVE MATERIALS - DETONATING CORD

ALWAYS handle detonating cord as carefully as other explosive materials.

ALWAYS cut the detonating cord from the spool before attempting to couple the cord to the rest of the explosive materials.

ALWAYS use a sharp knife, razor blade or instrument designed for cutting detonating cord.

ALWAYS attach detonators to detonating cord with tape or use methods recommended by the manufacturer.



ALWAYS point the detonators toward the direction of detonation.

NEVER make loops, kinks or sharp angles in the cord, which might direct the cord back toward the oncoming line of detonation.

NEVER cut detonating cord with devices such as scissors, pliers type cutters, or similar items.

NEVER attach detonators for initiating the blast to detonating cord until the blast area has been cleared and secured for the detonation.

NEVER use damaged detonating cord.

USING EXPLOSIVE MATERIALS - SAFETY FUSE & DETONATOR

General:

ALWAYS handle fuse carefully to avoid damaging the covering. In cooler weather, warm fuse slightly before use to avoid cracking the water proofing.

ALWAYS know the burning speed of the safety fuse by conducting a test burn of the fuse to be used.

NEVER use lengths of safety fuse less than three (3) feet.

NEVER insert safety fuse in the open end of a non-electric detonator in a rough manner.

NEVER use fuse, which has been kinked, bent sharply, or handled roughly in such a manner that the powder train may be interrupted.

Assembling Fuse and Detonator:

ALWAYS cut off an inch or two to ensure a dry end. Cut fuse squarely across with a tool designed for this purpose.

ALWAYS seat the fuse lightly against the detonator charge and avoid twisting after the fuse is seated.

ALWAYS ensure that the detonator is securely crimped to the fuse.

ALWAYS use cap crimpers to crimp the detonator to the safety fuse.

NEVER twist the fuse inside the detonator.

WORK SAFE 22 THINK SAFETY





NEVER use a knife or teeth for crimping.

NEVER cut fuse until you are ready to insert it into the detonator.

NEVER crimp detonators by any means except a cap crimper designed for that purpose.

NEVER attempt to remove a detonator from the fuse it is crimped to.

Lighting the Fuse:

ALWAYS light fuse with a fuse lighter designed for the purpose.

ALWAYS use the "buddy system" when lighting safety fuse - one lights the fuse, the other times and monitors.

NEVER hold explosives when lighting fuse.

NEVER use matches, cigarette lighters, cigarettes, pipes, cigars, or other unsafe means to ignite safety fuse.

AFTER DETONATION PROCEDURES

<u>Disposal of Explosive Materials</u>:

ALWAYS treat deteriorated or damaged explosive materials with special care. They are most likely more hazardous than explosive materials in good condition.

ALWAYS dispose of explosive materials using approved methods.

NEVER reuse any damaged explosive material packaging.

NEVER burn explosive materials packaging in a confined space.

Misfires:

ALWAYS wait at least thirty (30) minutes before approaching a misfire when safety fuse and non-electric detonator was used.

ALWAYS wait at least fifteen (15) minutes before approaching a misfire when an electric detonator was used.

ALWAYS shunt the bare wires of a misfired electric detonator by twisting them together and then tape them to the metal shell to protect against extraneous sources of electrical energy.

EZG



ALWAYS wait one (1) hour before approaching a misfire when a time delay fuse was used.

NEVER drill, bore, or pick out any explosive materials that have been misfired. Misfires should ONLY be handled by a competent, experienced person knowledgeable of the types, amounts, and location of all explosive materials involved in the misfire.

Detonation Fumes:

ALWAYS assume toxic fumes are present from all detonations or burning explosive materials and stay away until they have dissipated.

HAZARD COMMUNICATION

General:

The goal of a hazard communication program is to reduce the chance of illnesses and injuries to employees by providing as much information as needed to understand the hazards of the materials the employees may be exposed to in their work. This is accomplished through proper labeling of containers of hazardous materials, publishing a hazardous product list and preparing Material Safety Data Sheets (MSDSs).

In addition to the obvious hazard, encountered daily at the Explosive Products Center, other products, such as the following, can affect employees; Corrosives (acids), Irritants (solvents), Sensitizes (epoxies), and Toxins (carbon monoxide).

Labeling:

All containers of explosive materials, chemicals, etc. received from manufacturers or distributors should be properly labeled identifying the contents. In addition to relating the container contents, the label should identify the hazards associated with the contents and name and address of the manufacturer. No hazardous material shipment should be received if proper labels are not in place.

When transferring hazardous materials container contents into smaller containers, a proper label should be applied to the new container.

Containers with any explosive, or other hazardous material, should never be stored without proper labeling.

Hazardous Product List:

E 26



Each building/location where explosive operations are conducted will have a list of hazardous products used by employees in that operational location. The list should be in alphabetic order with the manufacturer's name. If an employee has any question about a product on the list, a Material Safety Data Sheet on that product should be requested.

Material Safety Data Sheets (MSDS):

These are technical data sheets prepared by manufacturers of hazardous, or potentially hazardous, materials. The MSDS should contain the following minimal information:

- a) Identification of the product, including the chemical and common names.
- b) Physical and chemical characteristics of the product.
- c) Known acute and chronic health effects and related information.
- d) Exposure Limit.
- e) Whether product is considered carcinogenic.
- f) Precautionary measures to take when using the product.
- g) Identification of person who prepared MSDS.
- h) Emergency and first aid procedures.

WORK SAFE



Standard Operating Procedures (SOP) SYSTEMS USING ELECTRIC DETONATORS

Service Supervisor (BLASTER) will have the blasting machine/firing device in his/her procession at all times.

- 1. Check the electric detonator and firing circuits with the **APPROVED** blasting multimeter or galvanometer. With the **detonator in the safety tube**.
- 2. Check the firing cable to ensure that it is properly shunted at the firing end.
- 3. With the detonator in the safety tube, connect the detonator lead wires to the firing cable.
- 4. Place the detonator/s securely into its position in the firing train.
- 5. All personnel will withdraw to the firing position making visual checks of the immediate vicinity to ensure that no unauthorized persons have entered the **LOCATION / BLAST SITE.**
- 6. Check the firing cable and connect to the appropriate blasting machine.
- 7. Sound audio warning system or predetermine signal.
- 8. Activate the blasting machine to initiate the explosive train.
- 9. Disconnect the blasting machine and shunt the firing line.
- 10. Allow at least one (1) minute to transpire before leaving the safety of the blast shelter or protected area.



Misfire Procedures - Whenever an electric firing system is utilized there is a possibility of a misfire. Should the first attempt to fire result in a misfire, at least two more attempts to initiate the blast will be made. If there is still no initiation, disconnect the blasting machine, shunt the firing cable and wait at least 15 minutes before approaching the Blast Site to investigate.

Because of the strong energy released by lightning, the loading of explosives should be suspended and personnel should be removed to a safe area at the approach and duration of an electrical storm, regardless of the initiation system.

SYSTEMS USING Exploding Bridgewire (EBW).

Service Supervisor (BLASTER) will have the control unit / fire set in his / her procession at all times.

- 1. Check the EBW detonator and firing circuits with the **APPROVED** blasting multimeter or galvanometer. Only the high voltage, low voltage cables and EBW can be checked, with the **detonator in the safety tube**.
- 2. Check the firing cable to ensure that it is properly shunted at the firing end.
- 3. With the detonator in the safety tube, connect the detonator lead wires to the firing cable.
- 4. Place the detonator/s securely into its position in the firing train.
- 5. All personnel will withdraw to the firing position making visual checks of the immediate vicinity to ensure that no unauthorized persons have entered the **LOCATION / BLAST SITE.**
- 6. Check the firing cable and connect to the appropriate control unit/fire set.
- 7. Sound audio warning system or predetermine signal.
- 8. Activate the control unit/fire set to initiate the explosive train.
- 9. Disconnect the control unit/fire set and shunt the firing line.

THINK SAFETY WORK SAFET



10. Allow at least one (1) minute to transpire before leaving the safety of the blast shelter or protected area.

Misfire Procedures - Whenever an electric firing system is utilized there is a possibility of a misfire. Should the first attempt to fire result in a misfire, at least two more attempts to initiate the blast will be made. If there is still no initiation, disconnect the control unit/fire set, shunt the firing cable and wait at least 15 minutes before approaching the Blast Site to investigate.

SYSTEMS USING NON- ELECTRIC DETONATORS

Safety Fuse in not approved for Specialty Services operations, only the Nonelectric initiation System and detonators.

Service Supervisor (BLASTER) will have the blasting machine/firing device in his/her procession at all times.

Although nonelectric firing systems are generally less susceptible to accidental firing by stray current or radio frequency energy than electric firing systems, they all contain sensitive primary explosives and pyrotechnics. As such, they should not be considered impervious to accidental initiation by lightning, static electricity, or strong electrical fields. Because of the strong energy released by lightning, the loading of explosives should be suspended and personnel should be removed to a safe area at the approach and duration of an electrical storm, regardless of the initiation system.

WORK SAFE